

TOP SECRET

Approved For Release 2002/05/07 : CIA-RDP78T04759A007400010004-2

PHOTOGRAPHIC INTERPRETATION REPORT



SARY-SHAGAN
R&D RADAR FACILITY 2
USSR

TCS-80608/67

SEPTEMBER 1967

COPY 203

2 PAGES

handle via **TALENT-KEYHOLE** control only

DECLASS REVIEW by NIMA/DOD

GROUP 1 EXCLUDED FROM
AUTOMATIC DOWNGRADING
AND DECLASSIFICATION

Approved For Release 2002/05/07 : CIA-RDP78T04759A007400010004-2

TOP SECRET

WARNING

This document contains Information affecting the national security of the United States within the meaning of the espionage laws U. S. Code Title 18, Sections 793 and 794. The law prohibits its transmission or the revelation of its contents in any manner to an unauthorized person, as well as its use in any manner prejudicial to the safety or interest of the United States or for the benefit of any foreign government to the detriment of the United States. It is to be seen only by personnel especially indoctrinated and authorized to receive Information in the designated control channels. Its security must be maintained in accordance with regulations pertaining to TALENT-KEYHOLE Control System.

Handle Via
Talent-KEYHOLE
Control System Only

Approved For Release 2002/09/08 : TOP SECRET RUFG 04759A007400010004-2-80608/17
September 197

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

NAME

Sary-Shagan R & D Radar Facility 2

25X1A

COUNTRY	GEO COORDINATES	WAC	BE NO	NPIC NO	COMOR NO
USSR	45-56N 73-38E	0245		2-D	
REFERENCES					

[REDACTED]

25X1D

Considerable progress is noted since [REDACTED] in a secured support facility under construction approximately 3,000 feet northeast of HEN ROOST Antenna North. The facility consists of 23 buildings, largely housing type, in various stages of construction. The facility buildings and service road can be negated on [REDACTED]. First evidence of road and building construction was noted on [REDACTED].

25X1D

25X1D

25X1D

Construction status of antennas at HEN ROOST NORTH and HEN ROOST SOUTH is undetermined on this mission. At HEN ROOST SOUTH a small building has been erected since [REDACTED] between the control building and the antenna. The number of crates has increased during this period just west of the antenna. Identification only is possible on the 3 suspect antennas south of the Support Area. A generally rectangular area of grading, approximately 375 by 295 feet, new since [REDACTED] and under work since [REDACTED] is observed just west of these suspect antennas.

25X1D


25X1D

Handle Via
Talent-KEYHOLE
Control System Only

Approved For Release 2008/06/01 : CIA-RDP78T04759A007400010004-2

~~TOP SECRET RUFF~~

TCS-80608/67
September 1967



25X1D

Approved For Release 2002/05/07 : CIA-RDP78T04759A007400010004-2

~~TOP SECRET~~

Approved For Release 2002/05/07 : CIA-RDP78T04759A007400010004-2

~~TOP SECRET~~